| DIF | FICUL | ITY | LOT# | ISSUE | | | | | 100000000000000000000000000000000000000 | |
|-------------|-------|-------------|------|--|--------------|--|--------|------------|---|-------------|
| 1 | | | 3 | Mildew on house | 1 | Just d | o i | t. No cost | involved to N | IOA |
| 1 | | | 9 | Trash cans exposed | | | | | | |
| 1 | | | 10 | Mildew on house | 2 | Small | CO | st to MOA | Possibly less | s then \$50 |
| 1 | | | 10 | Trash cans exposed | | | | | | |
| 1 | | | 11 | Trash cans exposed | 3 | Large o | CO | st to MOA | Possibly ove | r \$500 |
| 1 | | | 14 | Unapproved construction | | | | | | |
| 1 | | | 14 | Trash cans exposed | \top | | 1 | | | |
| 1 | | | 15 | Boat & trailer on side yard | T | | 1 | | | |
| 1 | | | 15 | Trash cans exposed | † | | \top | | | |
| 1 | | | 17 | Trash cans exposed | + | | + | | | |
| 1 | | | 21 | Yard Maintenance | + | | + | | | |
| 1 | | | 21 | Trash cans exposed | + | | + | | 1 | |
| 1 | | | 22 | Yard Maintenance | + | | + | | | |
| 4 | | | 30 | Yard Maintenance | + | | + | | | |
| | | | 30 | | + | | + | | | |
| 1 | | | | Parking on street/yard | + | | + | | | |
| 1 | | | 30 | Trash cans exposed | + | | + | | | |
| 1 | | | 32 | Unapproved paint color change | + | | 4 | | | |
| 1 | | | 33 | Trash cans exposed | | | | | | |
| 1 | | | 34 | Bottle brush tree needs trimmed | | | | | | |
| 1 | | | 46 | Rust Stain | | | | | | |
| 1 | | | 46 | Trash cans, wheel barrel, BBQ grill stored on driveway | | | | | | |
| 1 | | | 53 | Rust Stain | | | | | | |
| 1 | | | 56 | Boat in driveway | | | | | | |
| 1 | | | 56 | Trash cans exposed | | | | | | |
| 1 | | | HOA | rust stain on walls | 1 | | 1 | | | |
| (Table 200) | 2 | 1 | 7 | Fence needs repair/replace | + | | + | | | |
| | 2 | | 10 | Irrigation & AC equipment exposed | + | | + | | | |
| - | 2 | | 13 | Exposed Window A/C | + | | + | | 1 | |
| | 2 | | 21 | Irrigation & AC equipment exposed | + | | + | | | |
| | 2 | | 22 | Irrigation & AC equipment exposed | + | | + | | | |
| - | 2 | | 28 | AC equipment exposed | + | | - | | | |
| | 2 | | 31 | AC equipment exposed | + | Deline de la composición dela composición de la composición de la composición dela composición de la composición dela composición dela composición de la composición de la composición dela composición de la composición dela composición d | - | | | |
| | 2 | | 32 | | + | 7 | + | | | |
| | 2 | | | LP Gas tank exposed | + | | + | | | |
| | 2 | | 34 | Fence needs repair/replace | - | | + | | - | |
| | 2 | | 37 | Garage door needs repair | | | | | | |
| | 2 | | 51 | Pavers in driveway & sidewalk need repair | | | | | | |
| | 2 | | 53 | A/C & pool pump exposed | | | | | | |
| | 2 | | 56 | broken bathroom window | | | | | | |
| | 2 | | HOA | lack of maintenance of curbs | | | | | | |
| 2000 | 2 | | HOA | pothole and street signs in need of repair | | | | | | |
| | | 3 | 7 | Rotten Gable | | | | | | |
| | - | 3 | 7 | Rotten Wood Fascia | | | | | | |
| | | 3 | 9 | Non-conforming fence | T | | \neg | | | |
| | | 3 | 10 | Non-conforming fence | \top | | | | | |
| | | 3 | 10 | Missing Soffit | + | | + | | | |
| | | 3 | 10 | Rotten Wood on house | + | | + | | | |
| | 1 | 3 | 11 | Non-conforming fence | + | | + | | | |
| - | 2500 | 3 | 12 | Non-conforming fence | + | | + | | | |
| | | 2 | 22 | | + | | + | | - | |
| | | 3 | | Rotten Siding | - | | + | | - | |
| | | 3 | 29 | Non-conforming fence | 1 | | + | | 1 | |
| | | 3 | 32 | Non-conforming fence | - | | 1 | | | |
| | | 3 3 3 | 42 | Non-conforming fence | - | | 1 | | | |
| | | | 45 | Non-conforming fence | | | | | | |
| | | 3 | HOA | Non-conforming fence | | | | | | |
| | | | | | | | | | 4 | |
| 25 | 15 | 14 | 54 | | | | | | | |
| | 28% | | | | 1 | 9/17/14 | 4 | | | |